
ACCESSORY



S.5050
3000K CONVERSION FILTER

It is sometimes possible when installing the LIFT RECTANGULAR with metal halide lamps onto a whitewall, that there may be a difference in colour between the bottom light beam (~2700K) and the other (~3000K). This colour shift is caused by metal halide depositsforming on the bottom lamps arc tube, this problemcan be corrected by installing the 3000K conversionfilter inside the luminaire.

Exclusive distributor for USA
Sistemalux Inc. - 9320 Saint Laurent, Montréal (Qc) - Canada QC H2N 1N7 - Tel.: +1 (514) 523-1339

The present technical data sheet and all the information contained is property of SIMES S.p.A. All rights reserved.
We reserve the right to change specifications without prior written notice.